

ALERT TOPIC	Wind Blown Ply	ALERT REFERENCE:	CRL 080724
TARGET AUDIENCE:	Regional Managers, Site Managers Site Engineers and Supervisors Other interested people	AUTHORISED BY:	N Roper
DATE OF ISSUE:	Monday 8 July 2024	DISPLAY UNTIL:	01/12/24

## INTRODUCTION



A sheet of plywood was recently blown off a roof and landed in the street below.

The off cut of 3.6mm plywood, measuring 1200mm x 800mm, was caught by a gust of wind and blown over a parapet wall.

## **REASON FOR ISSUING THIS ALERT**

To remind people of the need to maintain good housekeeping and to consider materials that could fall, become dislodged or become airborne.

## **CONCLUSIONS AND DISCUSSION POINTS**

The site team had stopped working from cradles, due to the wind, and had started securing materials stored on the roof.





Please review the content of the attached SHEQ Alert for relevance prior to communicating the contents to your site teams. Please record this review on the form below and retain in the CRL filing system:

## SHEQ ALERT BRIEFING RECORD

ALERT TOPIC:	Wind Blown Ply	ALERT REFERENCE:	CRL 080724
PROJECT NAME:		DATE OF BRIEFING:	
BRIEFING DELIVERED BY:			

The following people have signed to confirm receipt and understanding of this SHEQ Alert:

NAME	EMPLOYER	EMPLOYEE ID	SIGNATURE

If you have any SHEQ issues that you wish to discuss, please contact your supervisor, line manager, or a member of the SHEQ team.



